Oil Field Environmental Incident Summary

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: CLEMENTINE 5693 44-35T

Field Name: ALGER Well File #: 26179

Date Incident: 2/6/2014 Time Incident: 1600 Facility ID Number:

County: MOUNTRAIL Twp: 156 Rna: 93 Sec: 35 Qtr: SE SE

Location Description:

Submitted By: Jared Iverson Received By:

Contact Person: Jared Iverson

1001 FANNIN STE 1500 HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well SiteReported to NRC: UnknownSpilledUnitsRecoveredUnitsFollowupUnitsOil0barrels0barrels40gallons

Brine0barrels0barrelsOther0barrels0barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/9/2016 Clean Up Concluded: 2/7/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts: None	
Action Taken or Planned: Plug was installed on valve. Contaminated soil cleaned up.	
Wastes Disposal Location:	
Agencies Involved:	
Updates	
Date: 2/7/2014 Status: Correspondence	Author: Stockdill, Scott
Updated Oil Volume:	
Updated Salt Water Volume:	
Updated Other Volume:	
Updated Other Contaminant	
Notes: Contacted company man.	
According to the company man, this spill was comprised of 1 bbl of clocation.	crude oil that was contained on
No followup necessary.	
Date: 2/7/2014 Status: Reviewed - Assigned to Other Agency	Author: Stockdill, Scott
Updated Oil Volume:	

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.